

Idle Fluctuation in Park or Neutral

Service Category Engine/Hybrid System

Section **Market** USA

Scion Supports
ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2015 - 2016	FR-S	

Introduction

Some 2015 – 2016 model year FR-S vehicles may exhibit a condition where the engine idle speed fluctuates (typically 500 – 1000 RPM) only when the transmission is in the Park or Neutral shift position. This condition occurs after the vehicle has been driven about 25 miles or more at highway speeds. The Transmission Control Module (TCM) logic has been revised to address this condition. Use the following procedure for reprogramming the TCM.

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VINs shown below.

MODEL	PLANT	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
FR-S	GUNMA	A/T	JF1ZNAA1#G#701603

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
EG1511	Reprogram the Transmission Control Module (TCM)	0.4	SU003-05270	8A	99

APPLICABLE WARRANTY

- This repair is covered under the Toyota Federal Emission Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

Idle Fluctuation in Park or Neutral

Parts Information

PART NUMBER	PART NAME	QTY
SU003-05270	Computer, Engine Control	1
00451-00001-LBL	Authorized Modification Labels	1

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream 2.0*	ADE	TS2UNIT	1
Techstream Lite		TSLITEPDLR01	

* Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 10.10.018 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- The Diagnostic Tester is NOT recommended for flash reprogramming. Please use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit techinfo.toyota.com for more information regarding J2534 reprogramming.



SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
GR8 Battery Diagnostic Station*	00002-MCGR8	1

NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

* Essential SST

Calibration Information


MODEL	ENGINE	CALIBRATION ID	
		PREVIOUS	NEW
FR-S	FA-20	AQF5DC70	AQF5DCB0

Idle Fluctuation in Park or Neutral

Repair Procedure

1. Confirm the condition as described in the Introduction.
2. Confirm calibration applicability.
3. Reprogram the TCM.
 - A. Check for the Authorized Modifications Label affixed to the vehicle in the location shown in Figure 1. Confirm if the TCM calibration has been updated. If the calibration ID listed is NOT the latest TCM calibration - go to step 3.B.

Figure 1. Location of Authorized Modification Label on 2015 FR-S



1	Replacement TCM Part Number (i.e., SU003-05270)
2	New Calibration ID(s) (i.e., AQF5DCB0)
3	Dealer Code

4	Date Completed
5	This SB Number

Idle Fluctuation in Park or Neutral

Repair Procedure (Continued)

B. Flash reprogram the TCM.

NOTE

- The GR8 Battery Diagnostic Station **MUST** be used in Power Supply Mode to maintain battery voltage at 13.5 volts while flash reprogramming the vehicle.
- For details on how to use the GR8 Battery Diagnostic Station, refer to the [GR8 Instruction Manual](#) located on the Technical Information System (TIS), Diagnostics – Tools & Equipment – Battery Diagnostics.

Follow the procedures outlined in Service Bulletin No. [S-SB-0015-14](#), “Techstream ECU Flash Reprogramming Procedure”, and flash the TCM with the NEW calibration file update.

C. Install the Authorized Modifications Label.

(1) Using a permanent marker, enter the following information on the label:

- ECM part number [Refer to the **Parts Information** section for the **CURRENT PART NUMBER**]
- Calibration ID(s) [Refer to the **Calibration Identification Chart** for the **NEW CALIBRATION ID**]
- Dealer Code
- Repair Date
- Change Authority [**This bulletin number**]

(2) Affix the Authorized Modifications Label to the vehicle at the location shown in Figure 1. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.

D. Start the engine and warm it up to normal operating temperature and test drive to confirm proper vehicle operation.