

Number: SB22-082

Issued: 14 July, 2022

# **SERVICE BULLETIN**

### **SUBARU CORPORATION**

Customer Quality Dept.

Japan.


Subject:	Part Change Information: New Part "POCKET ASSEMBLY" for BRZ	
Applicable Section in Service Manual:	Body & Electrical/WIRING SYSTEM > EXTERIOR/INTERIOR TRIM > Glove I	
Applicable Parts Name in Parts System:	Door, Seat, Windshield and Instrument Panel > INSTRUMENT PANEL > POCKET ASSEMBLY	
Foreword:	This Service Bulletin is to inform you of the new POCKET ASSEMBLY established as countermeasure part against the problem that POCKET ASSEMBLY is scratched by instrument panel installation bolt.	

### 1. Applicable Vehicle

Applicable Vehicle	Destination, Specification	MY
BRZ (LHD only)	North America, Europe, General	22 - 23

This information is applicable to Japan production vehicles only.

## 2. Details of the Symptom and Improvement



Service Bulletin Number: SB22-082

# 3. Production Change Information (Starting VIN)

Applicable Vehicle	Destination, Specification		Starting VIN
DDZ	North America		JF1ZDBE11P9700050
BRZ	Europe, General	LHD	JF1ZD8L81PG006001

For more detail of the VIN format, refer to the "Identification Section" in the Service Manual.

## 4. Parts Information and Interchangeability

No.	New Parts		Interchangeability	Old Parts	Note
1	Part No.	66121CC011	Now Dort to Old	66121CC010	North America
	Part Name	POCKET ASSEMBLY	New Part to Old Vehicle: <b>Yes.</b>	POCKET ASSEMBLY	
2	Part No.	66121CC021	Old Part to New	66121CC020	Europe
	Part Name	POCKET ASSEMBLY	Vehicle: <u><b>No.</b></u>	POCKET ASSEMBLY	General

## 5. Working Procedure

Refer to applicable vehicle Service Manual. The working procedure is not changed.

### 6. Labour Time

Refer to applicable vehicle Flat Rate Data.

END.

# CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

SUBARU Service Bulletins are intended for use by professional technicians **ONLY**. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, **DO NOT** assumes that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Service Bulletin Number: SB22-082