



# OREGON DEPARTMENT OF ENVIRONMENTAL QUALITY

## VEHICLE INSPECTION PROGRAM

**Overall Result - Fail**

### Station Information

DATE: 6/10/2021 11:18:30 AM TEST #: 1

STATION: 04

LANE: 3

UNIT: OR040302

INSPECTOR: Susan

### Vehicle Information

VIN: JF1ZCAC10D1610284  
Plate: 230LHX  
Vehicle Year: 2013  
Vehicle Make: Subaru  
Vehicle Model: BRZ

Cylinders: 4  
Body Type: 4  
Transmission: M  
Displacement: 2  
Class: P

Hybrid: No  
Fuel: G  
Weight Class: 0 to 6000 lbs

### OBD Sensor Status

Misfire:	Ready	2nd Air:	Unsupported
Fuel System:	Ready	Reserved:	Unsupported
Component:	Ready	O2 Sensor:	Ready
Catalyst:	Ready	O2 Heater:	Ready
Catalyst Heater:	Unsupported	EGR/VVT:	Ready
Evap:	Unsupported	COMM:	Pass
DLC:	Pass	MIL:	Pass

### Diagnostic Trouble Code(s)

The OBD test result indicates a lack of original manufacturer monitor support which is required for a valid test. It is a violation of Section 203(a)(3) of the Federal Clean Air Act to tamper with or to alter an OBD system from its original equipment configuration.

**Smoke Test:**

**Visual Inspection:** Pass

\* When repairs are made, your vehicle may not be ready for testing. The on-board system will need to update itself. A drive cycle is required to update the on-board computer. Please consult with your vehicle repair technician.

**NOTE:** Inspectors are prohibited from offering diagnostic information related to the vehicle readings or from making any estimates or recommendations regarding repairs or repair facilities.